



# **CITY OF LOMA LINDA**





**BENCH MARKS**

# City of Loma Linda Bench Mark Map



Not to Scale



## Bench Mark Types

- # Temporary Bench Mark
- ! Bench Mark

# Bench Marks

## Table of Contents

<b>Designations</b>	<b>Pages</b>
City of Loma Linda Bench Marks 1-31 (in order)	2-32
Gage Canal Co. Bench Mark	33
County of San Bernardino Bench Marks	34-36
NGS Bench Marks	37-38
USC&GS Bench Marks	39-45
USGS Bench Mark	46
City of Loma Linda Temporary Bench Marks 1-13 (in order)	47-59

DESIGNATION:

**LLBM 81-01**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP IN N.W. CORNER OF TOP OF CONC.  
BOX 4 FT. ABOVE GROUND OVER GAGE CANAL.  
280' SOUTH OF R.R. TRACK AND 50' NORTH AND 40'  
WEST OF CL AT DEAD END OF INDUSTRIAL ROAD

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1045.844

COMMENTS:

N/A





DESIGNATION:

**LLBM 81-02**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP ON TOP OF SOUTHERLY CONC.  
HEADWALL OF OUTLET STRUCTURE FOR GAGE  
CANAL, 45' NORTH OF NORTH CURB ON BARTON  
RD., 390' + / - EAST OF INT. OF BARTON RD. AND  
WATERMAN AVE.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1040.940

COMMENTS:

N/A



DESIGNATION:

**LLBM 81-03**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP IN SOUTHERLY CONC. SIGNAL LIGHT  
BASE N.E. CORNER AT INT. OF BARTON RD. AND  
UNIVERSITY AVE.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1062.309

COMMENTS:

N/A



DESIGNATION:

**LLBM 81-04**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP IN TOP OF CURB APPROX. AT M.O.C.  
OF S.E. CORNER AT INT. OF BARTON RD. AND  
SIERRA VISTA DR., 1' N.W. OF POWER POLE

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1147.090

COMMENTS:

N/A



DESIGNATION:

**LLBM 81-05**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP IN CONC. SIGNAL BASE, N.W. CORNER  
AT INT. OF BARTON RD. AND CAMPUS ST.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1152.045

COMMENTS:

N/A





DESIGNATION:

**LLBM 81-06**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP IN CONC. SIGNAL LIGHT BASE, N.W.  
CORNER AT INT. OF BARTON RD. AND ANDERSON  
ST.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1162.385

COMMENTS:

N/A



DESIGNATION:

**LLBM 81-07**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP ON CONC. SIGNAL LIGHT BASE, S.W.  
CORNER AT INT. OF UNIVERSITY AVE AND  
ANDERSON ST.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1115.480

COMMENTS:

N/A



DESIGNATION:

**LLBM 81-08**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP AT THE SOUTHEAST CORNER OF  
BARTON RD. AND BENTON ST. APPROXIMATELY 12"  
BEHIND CURB FACE.

TYPE

LLBM

DATE:


4/1/1988

ELEVATION:

1163.350

COMMENTS:

N/A



DESIGNATION:

**LLBM 81-09**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP IN CONC. SIGNAL LIGHT BASE, N.W.  
CORNER AT INT. OF BARTON RD. AND MOUNTAIN  
VIEW AVE.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1195.247

COMMENTS:

N/A



DESIGNATION:

**LLBM 81-10**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

BRYN MAWR

DESCRIPTION:

BRASS CAP IN N.E. CORNER OF DROP INLET BOX 1'  
BACK OF CURB SOUTH SIDE OF BARTON  
FRONTAGE RD., 111 FT. WEST OF CL INT. BRYN  
MAWR AVE. AND BARTON FRONTAGE RD.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1182.012

COMMENTS:

N/A



DESIGNATION:

**LLBM 81-11**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

BRYN MAWR

DESCRIPTION:

BRASS CAP IN TOP OF CURB 1.5' NORTH OF  
NORTH CURB RET., 1/2' EAST OF P.P NO. 1960432 E  
AT N.W. CORNER INT. OF BARTON RD. AND  
CALIFORNIA ST.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1200.079

COMMENTS:

N/A





DESIGNATION:

**LLBM 81-12**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP ON SIDEWALK 1' SOUTH OF CURB 1'  
NORTH OF STREET SIGN AT S.W. CORNER INT. OF  
ANDERSON ST. AND LAWTON AVE., 9' EAST OF  
WEST RETURN

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1214.111

COMMENTS:

N/A



DESIGNATION:

**LLBM 81-13**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP IN N.E. CORNER OF OARKWAY DRAIN  
SOUTH SIDE OF LAWTON AVE., 23' SOUTH AND 50'  
WEST OF CL INT. OF LAWTON AVE. AND POPLAR  
ST.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1200.714

COMMENTS:

N/A



DESIGNATION:

**LLBM 81-14**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP IN CONC. SIDEWALK 1' WEST OF CURB,  
2' N.E. OF STREET SIGN AT SOUTH END OF CURB  
RET., S.W. CORNER AT INT. OF TULIP AVE. AND  
HILLCREST ST.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1177.938

COMMENTS:

N/A



DESIGNATION:

**LLBM 81-15**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP IN N.E. CORNER OF CONC. DROP INLET  
BOX, EAST SIDE OF PECAN WAY, 4' SOUTH OF  
CURB RET. AT S.E. CORNER OF INT. HURON ST.  
AND PECAN WAY

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1267.206

COMMENTS:

N/A



DESIGNATION:

**LLBM 81-16**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP IN SIDE WALK 1' BACK OF CURB AT  
WEST CURB RET., S.W. CORNER OF INT. HURON  
ST. AND LOMA LINDA DR.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1255.202

COMMENTS:

N/A



DESIGNATION:

**LLBM 81-17**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP IN S.E. CORNER OF CONC. DROP INLET  
BOX 1' BACK OF CURB. 25' SOUTH OF SOUTH CURB  
RET. AT S.E. CORNER OF INT. OF MOUNTAIN VIEW  
AVE. AND LAWTON AVE.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1241.953

COMMENTS:

N/A





DESIGNATION:

**LLBM 81-18**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP IN CONC. STREET LIGHT BASE 1' BACK  
OF CURB AT NORTH END OF CURB RET. AT N.E.  
CORNER INT. OF MOUNTAIN VIEW AVE. AND  
BEAUMONT AVE.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1306.316

COMMENTS:

January 18, 2006: Verified location.



DESIGNATION:

**LLBM 81-19**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP IN TOP OF RETAINING WALL 1/2'  
NORTH OF POWER POLE, 25' WEST AND 15' SOUTH  
OF CL INT. BRYN MAWR AVE. AND BEAUMONT AVE.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1336.592

COMMENTS:

January 18, 2006: Went to verify location,  
unable to locate.



DESIGNATION:

**LLBM 81-20**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

BRYN MAWR

DESCRIPTION:

BRASS CAP IN CONC. HEADWALL OF IRRIGATION  
DITCH NORTH SIDE OF BEAUMONT AVE., 400' +/-  
EAST OF INT. BEAUMONT AVE. AND WHITTIER AVE.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1332.737

COMMENTS:

January 18, 2006: Went to verify location,  
unable to locate.



DESIGNATION:

**LLBM 81-21**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

BRYN MAWR

DESCRIPTION:

BRASS CAP IN TOP OF CONC. HEADWALL FOR  
IRRIGATION DITCH, SOUTH SIDE OF SECOND ST.  
1320' +/- EAST OF WHITTIER AVE., BETWEEN 4TH  
AND 5TH POWER POLE EAST OF WHITTIER AVE.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1264.521

COMMENTS:

N/A



DESIGNATION:

**LLBM 81-22**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP IN TOP OF CURB WEST SIDE OF BRYN MAWR AVE., 18' NORTH AND 22' WEST OF CL INT. OF SECOND ST. AND BRYN MAWR AVE.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1261.926

COMMENTS:

N/A



DESIGNATION:

**LLBM 81-23**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP IN N.E. CORNER OF DROP INLET, 1'  
BEHIND CURB RET. AT S.W CORNER INT. OF  
LAWTON AVE. AND BRYN MAWR AVE.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1219.247

COMMENTS:

N/A





DESIGNATION:

**LLBM 81-24**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

BRYN MAWR

DESCRIPTION:

BRASS CAP IN NORTH WEST CORNER OF CONC.  
BLOCK WEIR BOX, 40' NORTH OF CL OF MISSION  
RD. AND 40' EASTERLY OF TRANSFORMER POLE  
NO. OF 344481E, 0.30 MI. WESTERLY CALIFORNIA  
ST. ALONG MISSION RD.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1176.658

COMMENTS:

N/A



DESIGNATION:

**LLBM 81-25**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP IN SIDEWALK 1' SOUTH OF S.W.  
CORNER OF 4' HIGH GUACHANA RANCHERRA  
MONUMENT (HISTORICAL LANDMARK NO. 35), 35'  
NORTH OF CL OF MISSION ROAD. APPROX. 60' +/-  
WEST FROM EDISON TRANSMISSION LINES 0.30 MI.  
EASTERLY OF MT. VIEW AVE. ALONG MISSION RD.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1136.566

COMMENTS:

N/A



DESIGNATION:

**LLBM 81-26**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP IN S.W. CORNER OF CONC. DROP  
INLET, 1' BEHIND CURB, 7' SOUTH OF SOUTH CURB  
RET. AT S.E. CORNER INT. OF MOUNTAIN VIEW  
AVE. AND MISSION RD.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1123.436

COMMENTS:

N/A



DESIGNATION:

**LLBM 81-27**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP IN SIDEWALK 1' BEHIND WEST CURB AT SOUTH END OF ABUTMENT FOR MOUNTAIN VIEW AVE. BRIDGE OVER SAN TIMOTEO CREEK, 1' NORTH OF NORTH CURB RET., N.W. CORNER OF INT. OF MOUNTAIN VIEW AND JUANITA ST.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1148.750

COMMENTS:

February 7, 2006: Verified location.



DESIGNATION:

**LLBM 81-28**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP IN TOP OF CONC. CURB NEAR M.O.C.  
OF CURB RET., N.E. CORNER AT INT. OF REDLANDS  
BLVD. AND BRYN MAWR AVE., 0.54 MILES EAST OF  
MOUNTAIN VIEW AVE. ALONG REDLANDS BLVD.

TYPE

LBM

DATE:


1/1/1981

ELEVATION:

1135.579

COMMENTS:

N/A



DESIGNATION:

**LLBM 81-29**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP IN N.E. CORNER OF CONC. CATCH  
BASIN ON SOUTH SIDE OF REDLANDS BLVD., 112'  
EAST OF CL INT. REDLANDS BLVD. AND  
RICHARDSON ST.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1092.594

COMMENTS:

N/A





DESIGNATION:

**LLBM 81-30**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP IN N.W. CORNER OF CONC. BASE FOR  
LIGHT STD. NO. 2114767E, 3' SOUTH OF A.C. BERM  
AT SOUTH END OF RICHARDSON ST.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1297.228

COMMENTS:

N/A



DESIGNATION:

**LLBM 81-31**

ESTABLISHED:

CITY OF LOMA LINDA

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP IN S.E. CONC. PIER OF SOUTHERN CALIFORNIA EDISON TOWER (DEVER - VISTA NO. 1 3/4), 1500' +/- SOUTH AND 300' +/- EAST OF SOUTH END OF RICHARDSON ST.

TYPE

LLBM

DATE:


1/1/1981

ELEVATION:

1479.274

COMMENTS:

N/A



DESIGNATION:

ESTABLISHED:

VICINITY:

**GAGE CANAL COMPANY**

GAGE CANAL COMPANY

LOMA LINDA

DESCRIPTION:

BRASS CAP IN TOP OF CURB NORTH SIDE OF  
REDLANDS BLVD., APPROX. AT CL OF GAGE CANAL  
0.5 MI. WEST OF INTERSECTION OF ANDERSON  
ST. AND REDLANDS BLVD.

TYPE

GAGE CANAL

DATE:


1/1/1981

ELEVATION:

1042.385

COMMENTS:

N/A



DESIGNATION:

ESTABLISHED:

VICINITY:

**SB CO BM 12-1**

SAN BERNARDINO COUNTY

BRYN MAWR

DESCRIPTION:

0.1 MI. SO. OF BARTON RD. & CALIFORNIA ST. SET  
DRIVE PIN W/C.S. TAG, 1 FOOT NO. S.P.R.R.  
TRESSEL, 6 1/2' E. OF E. RAIL S.P. SPUR TRACKS  
NO. SIDE OF SAN TIMOTEO WASH.

TYPE

SB CO BM

DATE:


1/1/1981

ELEVATION:

1204.352

COMMENTS:

January 25, 2006: Went to verify location,  
unable to locate. Believed to be  
underground due to construction of San  
Timoteo Channel.



DESIGNATION:

**SB CO BM12-2**

ESTABLISHED:

SAN BERNARDINO COUNTY

VICINITY:

BRYN MAWR

DESCRIPTION:

0.5 MI. NORTH ALONG CALIFORNIA ST. FROM  
INTERSECTION OF BARTON RD. & CALIFORNIA ST.,  
SET BRASS DISK IN S.W. CORNER W. HEAD WALL  
FOR S.P. SPUR TRACKS, 96' E. OF CALIFORNIA ST.  
0.1 MI. SOUTH OF CENTERLINE CITRUS AVE. LEVEL  
WITH TRACKS, 125' N.E. OF PP #239

TYPE

SBCO

DATE:

1/1/1981

ELEVATION:

1177.833

COMMENTS:

January 17, 2006: Went to verify location,  
unable to locate.



DESIGNATION:

ESTABLISHED:

VICINITY:

**NGS S-1327**

NGS

LOMA LINDA

DESCRIPTION:

BRASS CAP IN WEST FOOTING OF RAILROAD  
SIGNAL SUPPORT, SOUTH SIDE OF RAILROAD  
TRACKS, 120' EAST OF CL AT DEAD END OF  
BENTON ST.

TYPE

NGS

DATE:


1/1/1981

ELEVATION:

1113.245

COMMENTS:

N/A



DESIGNATION:

**SB CO BM 12-3**

ESTABLISHED:

SAN BERNARDINO COUNTY

VICINITY:

BRYN MAWR

DESCRIPTION:

1.0 MI. NO. ALONG CALIFORNIA ST. FROM  
INTERSECTION OF BARTON RD. & CALIFORNIA ST.  
AT THE INTERSECTION OF CALIFORNIA ST. &  
REDLANDS BLVD., SET BRASS DISK IN MIDDLE OF  
S.W. WING WALL OF BRIDGE #54-08, 48' SO. OF CL  
REDLANDS BLVD., 22' E. OF CL CALIFORNIA ST., 1'  
LOWER THAN REDLANDS BLVD., ACROSS THE  
STREET FROM MISSION SCHOOL GROUNDS

TYPE

SB CO BM

DATE:


1/1/1981

ELEVATION:

1160.408

COMMENTS:

January 25, 2006: Verified location. At  
intersection of Redlands Blvd. and  
California St.



DESIGNATION:

**NGS T-1327**

ESTABLISHED:

NGS

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS CAP SET IN CONC. 0.5 MI. NORTH OF INT.  
MOUNTAIN VIEW AVE. AND BARTON RD. BENEATH  
MOUNTAIN VIEW AVE. R.R. BRIDGE, 15' EAST OF  
WEST EDGE OF BRIDGE, 12' SOUTH OF SOUTH  
RAIL, 0.7' BELOW TOP OF RAIL

TYPE

NGS

DATE:


1/1/1981

ELEVATION:

1149.168

COMMENTS:

N/A





DESIGNATION:

ESTABLISHED:

VICINITY:

**USC&GS BRYN**

USC&GS

LOMA LINDA

DESCRIPTION:

BRONZE TRIANGULATION STA. DISK 0.2 MI. WEST REDLANDS BLVD. AND ANDERSON ST., 26.2' NORTH OF THE CL OF THE NORTH TRAFFIC LANES OF THE BLVD., 4' NORTH OF P.P. NO. 18720 C.W.T., 4 1/2' BEHIND CURB, ABOUT 1' HIGHER THAN THE HIGHWAY, AND SET IN THE TOP OF A CONC. POST PROJECTING 0.2' ABOVE THE GROUND

TYPE

USC&GS

DATE:


1/1/1981

ELEVATION:

1052.765

COMMENTS:

February 7, 2006: Verified location.



DESIGNATION:

**USC&GS LINDA**

ESTABLISHED:

USC&GS

VICINITY:

LOMA LINDA

DESCRIPTION:

BRONZE TRIANGULATION STA. DISK 0.65 MI.  
SOUTH ALONG TRAIL FROM END OF SIERRA VISTA  
DR., ON SOUTHEASTERN END OF LONG RIDGE,  
AND ABOUT 300' NORTH OF BARREN SPOT  
MARKING HIGHEST PORTION OF RIDGE, JUST IN  
FRONT OF STEEP DECLINE, SET IN 10 IN. SQUARE  
CONC. POST, 2' EAST OF 3' HIGH FENCE POST

TYPE

USC&GS

DATE:


1/1/1981

ELEVATION:

1586.074

COMMENTS:

N/A



DESIGNATION:

ESTABLISHED:

VICINITY:

**USC&GS V 71 RESET 1939**

USC&GS

LOMA LINDA

DESCRIPTION:

BRONZE DISK ABOUT 105' SOUTH OF THE SOUTH RAIL OF THE MAIN LINE TRACK, 41' EAST OF THE CL OF PARKLAND ST., 18' EAST OF EAST CURB, 1' NORTH OF A WITNESS POST, SET IN THE TOP OF A CONC. POST PROJECTING 0.6' ABOVE THE GROUND

TYPE

USC&GS

DATE:


1/1/1981

ELEVATION:

1079.680

COMMENTS:

N/A



DESIGNATION:

ESTABLISHED:

VICINITY:

**USC&GS C 524**

USC&GS

LOMA LINDA

DESCRIPTION:

BRASS DISK AT THE INT. OF REDLANDS BLVD. AND MT. VIEW AVE. 23.0' NORTH OF THE NORTH CURB OF REDLANDS BLVD., 2.1' EAST OF THE EAST CURB OF MT. VIEW AVE., 11' SOUTH OF P.P. 1789141E, ABOUT 1/2' HIGHER THAN THE AVE., AND SET IN TOP OF A CONC. POST PROJECTING 0.4' ABOVE GROUND

TYPE

USC&GS

DATE:


1/1/1981

ELEVATION:

1113.360

COMMENTS:

N/A



DESIGNATION:

**USC&GS H 525**

ESTABLISHED:

USC&GS

VICINITY:

BRYN MAWR

DESCRIPTION:

BRASS DISK 0.4 MI. S.E. ALONG THE SOUTHERN PACIFIC RAILROAD CO. R.R. FROM THE STATION AT BRYN MAWR, 39.7' EAST OF THE EAST RAIL, 11' EAST OF THE CL OF A TRACK ROAD, 2.6' EAST OF THE 1ST POLE WEST OF MILEPOST 545, 1.7' WEST OF A WITNESS POST, ABOUT 1' HIGHER THAN THE TRACK, AND SET IN A CONC. POST PROJECTING 0.5' ABOVE GROUND

TYPE

USC&GS

DATE:


1/1/1981

ELEVATION:

1231.057

COMMENTS:

February 7, 2006: Went to verify location, unable to locate.



DESIGNATION:

ESTABLISHED:

VICINITY:

**USC&GS G 527 RESET 1996** USC&GS

LOMA LINDA

DESCRIPTION:

STANDARD DISK LOCATED 0.5 MI. NORTH ALONG ANDERSON ST. FROM THE CROSSING OF THE SOUTHERN PACIFIC CO. R.R. AT LOMA LINDA, AT THE INTERSECTION OF REDLANDS BLVD., IN THE TOP OF THE NORTH END OF THE N.E. CURB RET.

TYPE

USC&GS

DATE:


8/30/1996

ELEVATION:

1064.854

COMMENTS:

N/A



DESIGNATION:

**USC&GS J 527**

ESTABLISHED:

USC&GS

VICINITY:

LOMA LINDA

DESCRIPTION:

BRASS DISK 0.30 MI. NORTH ALONG ANDERSON ST.  
FROM THE CROSSING OF THE SOUTHERN PACIFIC  
CO. R.R., AT THE LOMA LINDA ACADEMY, SET  
VERTICALLY IN THE EAST FACE OF THE SOUTH  
CONCRETE COLUMN AT THE MAIN ENTRANCE, 96.4'  
WEST OF THE CL OF THE STREET 1.2' SOUTH OF  
THE SOUTH EDGE OF THE ENTRANCE AND 0.7'  
ABOVE THE ENTRANCE FLOOR

TYPE

USC&GS

DATE:


1/1/1981

ELEVATION:

1073.730

COMMENTS:

January 25, 2006: Verified location.



DESIGNATION:

**USGS 1201**

ESTABLISHED:

USGS

VICINITY:

LOMA LINDA

DESCRIPTION:

BRONZE CAP AT RAILROAD CROSSING B544.5  
(WHITTIER AVE.), 11 1/2' EAST OF P.P. NO.  
1407053E, 17' WEST OF THE CL OF WHITTIER AVE.,  
13' SOUTH OF THE CENTER OF CULVERT 544.47  
AND RIVETED ON TOP OF A 3 1/2 INCH IRON PIPE  
PROJECTING 0.6' ABOVE GROUND, 51' SOUTH OF  
THE SOUTH TRACK OF THE MAINLINE, AND IN LINE  
WITH THE SOUTH RIGHT OF WAY FENCE

TYPE

USGS

DATE:

1/1/1981

ELEVATION:

1201.445

COMMENTS:

N/A





DESIGNATION:

ESTABLISHED:

VICINITY:

**TBM NO. 1**

CITY OF LOMA LINDA

LOMA LINDA

DESCRIPTION:

TYPE

DATE:

ELEVATION:

SPIKE IN SIDEWALK 1' BEHIND CURB ON WEST  
SIDE OF MOUNTAIN VIEW AVE. AT THE SOUTH END  
OF ABUTEMENT FOR BRIDGE OVER RAILROAD  
TRACKS


TBM

1/1/1981

1182.089

COMMENTS:

February 7, 2006: Verified location, no ID.



DESIGNATION:

ESTABLISHED:

VICINITY:

**TBM NO. 2**

CITY OF LOMA LINDA

LOMA LINDA

DESCRIPTION:

TYPE

DATE:

ELEVATION:

SPIKE IN SIDEWALK 1' BEHIND CURB ON WEST  
SIDE OF MOUNTAIN VIEW AVE. AT SOUTH END OF  
BRIDGE OVER RAILROAD TRACKS


TBM

1/1/1981

1181.533

COMMENTS:

February 7, 2006: Verified location, no ID.



DESIGNATION:

ESTABLISHED:

VICINITY:

**TBM NO. 3**

CITY OF LOMA LINDA

LOMA LINDA

DESCRIPTION:

TYPE

DATE:

ELEVATION:


SPIKE IN SIDEWALK 1' BEHIND CURB ON WEST  
SIDE OF MOUNTAIN VIEW AVE. APPROXIMATELY IN  
MIDDLE OF BRIDGE OVER RAILROAD TRACKS

TBM

11/19/6855 1179.460

COMMENTS:

February 7, 2006: Verified location, no ID.



DESIGNATION:

ESTABLISHED:

VICINITY:

**TBM NO. 4**

CITY OF LOMA LINDA

LOMA LINDA

DESCRIPTION:

TYPE

DATE:

ELEVATION:

SPIKE IN SIDEWALK 1' BEHIND CURB ON WEST  
SIDE OF MOUNTAIN VIEW AVE. AT NORTH END OF  
BRIDGE OVER RAILROAD TRACKS


TBM

1/1/1981

1177.524

COMMENTS:

February 7, 2006: Verified location, no ID.



DESIGNATION:

ESTABLISHED:

VICINITY:

**TBM NO. 5**

CITY OF LOMA LINDA

LOMA LINDA

DESCRIPTION:

TYPE

DATE:

ELEVATION:

SPIKE IN SIDEWALK 1' BEHIND CURB ON WEST  
SIDE OF MOUNTAIN VIEW AVE. AT NORTH END OF  
NORTH ABUTEMENT FOR BRIDGE OVER RAILROAD  
TRACKS


TBM

1/1/1981

1176.036

COMMENTS:

February 7, 2006: Verified location, no ID.



DESIGNATION:

ESTABLISHED:

VICINITY:

**TBM NO. 6**

CITY OF LOMA LINDA

LOMA LINDA

DESCRIPTION:

TYPE

DATE:

ELEVATION:

SPIKE IN SIDEWALK 1/2' BEHIND BEHIND CURB ON  
WEST SIDE OF MOUNTAIN VIEW AVE. AT SOUTH  
END OF BRIDGE OVER SAN TIMOTEO CREEK


TBM

1/1/1981

1147.742

COMMENTS:

February 7, 2006: Verified location, no ID.



DESIGNATION:

ESTABLISHED:

VICINITY:

**TBM NO. 7**

CITY OF LOMA LINDA

LOMA LINDA

DESCRIPTION:

TYPE

DATE:

ELEVATION:

SPIKE IN SIDEWALK 1' BEHIND CURB ON WEST  
SIDE OF MOUNTAIN VIEW AVE. APPROXIMATELY AT  
MIDDLE OF BRIDGE OVER SAN TIMOTEO CREEK


TBM

1/1/1981

1145.098

COMMENTS:

February 7, 2006: Verified location, no ID.



DESIGNATION:

ESTABLISHED:

VICINITY:

**TBM NO. 8**

CITY OF LOMA LINDA

LOMA LINDA

DESCRIPTION:

TYPE

DATE:

ELEVATION:

SPIKE IN SIDEWALK 1/2' BEHIND CURB ON WEST  
SIDE OF MOUNTAIN VIEW AVE. AT NORTH END OF  
BRIDGE OVER SAN TIMOTEO CREEK


TBM

1/1/1981

1142.679

COMMENTS:

February 7, 2006: Verified location, no ID.





DESIGNATION:

ESTABLISHED:

VICINITY:

**TBM NO. 9**

CITY OF LOMA LINDA

LOMA LINDA

DESCRIPTION:

SPIKE IN SIDEWALK 1' BEHIND CURB ON WEST  
SIDE OF MOUNTAIN VIEW AVE. AT NORTH END OF  
NORTH ABUTEMENT FOR BRIDGE OVER SAN  
TIMOTEO CREEK

TYPE

TBM

DATE:


1/1/1981

ELEVATION:

1141.843

COMMENTS:

February 7, 2006: Went to verify location,  
unable to locate.



DESIGNATION:

ESTABLISHED:

VICINITY:

**TBM NO. 10**

CITY OF LOMA LINDA

LOMA LINDA

DESCRIPTION:

TYPE

DATE:

ELEVATION:

SPIKE IN TOP OF CURB AT EAST SIDE OF POPLAR ST. 18' EAST AND 3' SOUTH OF CL OF INTERSECTION OF ASPEN AVE. AND POPLAR ST.

TBM

1/1/1981

1178.41

COMMENTS:

N/A



DESIGNATION:

ESTABLISHED:

VICINITY:

**TBM NO. 11**

CITY OF LOMA LINDA

BRYN MAWR

DESCRIPTION:

TYPE

DATE:

ELEVATION:

SPIKE IN P.P. NO. 1002416E 40' SOUTH OF CL  
MISSION RD. 0.25 MILE WESTERLY OF CALIFORNIA  
ST, ALONG MISSION RD.


TBM

1/1/1981

1178.72

COMMENTS:

August 15, 2005: Went to verify location,  
unable to locate.



DESIGNATION:

ESTABLISHED:

VICINITY:

**TBM NO. 12**

CITY OF LOMA LINDA

LOMA LINDA

DESCRIPTION:

TYPE

DATE:

ELEVATION:

CONC. NAIL ON FENCE POST BASE, THIRD POST  
WEST OF TRAIL 2000' +/- SOUTH ALONG NATURAL  
FLOW LINE FROM END OF SIERRA VISTA DR.


TBM

1/1/1981

1366.70

COMMENTS:

N/A



DESIGNATION:

ESTABLISHED:

VICINITY:

**TBM NO. 13**

CITY OF LOMA LINDA

LOMA LINDA

DESCRIPTION:

TYPE

DATE:

ELEVATION:

SPIKE IN P.P. NO. 1733461E AT WEST SIDE OF AND  
AT SOUTH END OF SIERRA VISTA DR. 700' +/-  
SOUTH OF INTERSECTION OF BARTON RD. AND  
SIERRA VISTA DR.

TBM

1/1/1981

1215.15

COMMENTS:

N/A

